




Instruction:

- 1.The terminals on the wires should be clamped, with 50N tension can not be loosened;
2. In strict accordance with the drawing standards, specifications, length of wiring;
3. Main power cable 4MM2,Compressor cable 2.5MM2,other cables 1MM2.